

PREPARATION OF POLY-L-LYSINE COATED SLIDES

1. Buy acid washed slides.
2. Dip slides in $500 \mu\text{gml}^{-1}$ poly-l-lysine, 10 mM Tris pH 8.0 for 10' at room temperature. (40 ml solution coats 40 slides).
3. Air dry in a dust free place.
4. Store at room temperature for several weeks.

Alternative: Buy coated slides from BDH!